


# PLASMA-POINT®

## CZĘŚCI ZAMIENNE DO:

TRUMPF®  
TLC 105



Poz.	Numer ref.	Kod (std.)	Kod (chrom.)	Opis
1	212334	212334	212334/C	Dysza ø1.0mm. HP
	216199	216199	216199/C	Dysza ø 1.4mm.HP
	225213	225213	225213/C	Dysza ø 1.7mm. HP
	126156	126156	126156/C	Dysza ø 2.3mm. HP
	237364	237364	237364/C	Dysza ø 1.0mm. Prysznic
2	226939	226939	226939/C	Dysza ø 1.0mm. Standart
	226940	226940	226940/C	Dysza ø 1.4mm. Standart
	227144	227144	227144/C	Dysza ø 1.7mm.
	227145	227145	227145/C	Dysza ø 2.3mm.
3	-----	135320/S	135320/S/C	Dysza ø 1.0mm.
	-----	135318/S	135318/S/C	Dysza ø 1.4mm. HD.
	-----	126157/S	126157/S/C	Dysza ø 1.7mm. HD
4	135320	135320	135320/C	Dysza ø 1.0mm. HD
	135318	135318	135318/C	Dysza ø 1.4mm. HD
	126157	126157	126157/C	Dysza ø 1.7mm. HD
5	913803	913803	913803/C	Dysza ø 2.3mm. HD
6	P0494-752-00001	<b>280408</b>	-----	<b>Obsada dyszy, oryginal</b>
7	0936678	936678	-----	Obsada dyszy (nasza produkcja)