


PLASMA-POINT®

CZĘŚCI ZAMIENNE DO:

TRUMPF®
TLC 1005



Poz.	Numer ref.	Kod (std.)	Kod (chrom.)	Opis
1	0913799 0913800	0913799 0913800	0913799/C 0913800/C	Dysza \varnothing 0.8mm. Dysza \varnothing 1.0mm.
2	0913801	0913801	0913801/C	Dysza \varnothing 1.4mm.
3	0937988	0937988	0937988/C	Dysza \varnothing 1.7mm.
4	0937989	0937989	0937989/C	Dysza \varnothing 2.3mm.
5	0913965	0913965	0913965/C	Dławik
6	0936678	936678	-----	Obsada dyszy (nasza produkcja)